

25X1
28 APR 63 1826Z

SECRET

DIRECTOR

ROUTINE

25X1
25X1
25X1
TOR 28 APR 63 1936Z

74095

- 25X1
25X1
25X1
- A. GF 63-19.
B. 358.
C. 27 APR 63 5 PLUS 10.
D. FERRY FLT FOR [REDACTED] IFF.
E. [REDACTED] INOPERATIVE - REPLACE BROKEN CIRCUIT BREAKER.
F. OIL IN TAILPIPE - GROUND RUN FOR LEAKS, 2 HR FLIGHT TEST FOR LEAKS AND/OR CONSUMPTION CHECK.
G. NONE.
A. GM 63-23.
B. 358.
C. 23 APR 63 1 PLUS 50.
D. LOW ALT TEST FLIGHT TO CHECK POSS OIL LEAK AND CONSUMPTION;
[REDACTED]
E. [REDACTED] STILL INOPERATIVE - CORRECTIVE ACTION UNK AT THIS TIME.
F. NONE.

25X1
25X1
G. NO OIL LEAKS FOUND INSIDE OR OUTSIDE ENG AT POST FLT INSPECTION. OIL CONSUMPTION LESS THAN ONE QUART.

END OF MESSAGE

SECRET